



084.02:40-02:48: 8m RT 1024bps data lost at DSS24  
due to procedural problem with U/L configuration  
leading to delayed U/L & long s/c transition from 1-  
way to 2-way. DR G100930 refers.